Minutes of the Lakeside Village Combined Committee Meeting

June 13, 2012 at 7:00PM

1. Introductions/Role Call -

M&G	Х	
С	Х	
	Х	
M&G	Х	
С		X
M&G		X
С	Х	
M&G	Х	
	C M&G C M&G C	C X X X M&G X C M&G C X

2. Maintenance and Grounds (M&G) Issues -

a. Follow-up from last meeting -

The May 2012 Action Item Tracking Sheet was reviewed and completed items were removed.

Fire Alarm System – Owners have approved by at least 60% the installation of the alarm system in all five buildings and have the fire department automatically notified.

b. New Items -

The June 2012 Action Item Tracking Sheet was annotated with several new items.

The LSV Scheduled Maintenance Sheet was reviewed. Committee members will bring ideas to the next meeting for making additions and changes to the Sheet.

The Committee reviewed a walkway repair list.

3. Communication Issues -

A sign-up calendar will be placed on the Cabana bulletin board so that people who reserve the Cabana can annotate their unit number, date, and time. This will help prevent double booking of the Cabana.

4. Community Watch Status -

With Board concurrence, the Committee would like to invite the city of Federal Way to make a presentation at our July Board Meeting. The Committee would also attend. Home owners would also be invited.

- 5. New committee members We still need new Committee members from Buildings 1, 2, and 4.
- 6. Adjourn -8:35 PM

Submitted by

Jim Johnson

1 Attach: June 2012 Action Item Tracking Sheet

Lakeside Village Maintenance & Grounds Committee Action Item Tracking for June, 2012

		Board or	Estimated			
		Committee	Completion	Work order		Date
Date Added	Name/ Task	Priority	Date	Issue Date	Property Manager Status	Complete
	Gutters Bldg 5 (check on another way to	Н				
11/17/2011	prevent overflowing)		17-Apr			
	Gutter at parking spot 4 rusted					
12/11/2001	through/leaking and full of leaves.	Н	17-Apr	27-Mar		4/13/2012 ?
12/11/2001	Downspout crushed shut. Gutter at parking spot 16 full of branches		17-Apr	27-IVIa1		4/13/2012 !
2/8/2012	and leaves.	Н	17-Apr	27-Mar		4/13/2012 ?
2,0,2012	Gutters on street side of parking spot 72		±7,7(p)	27 17101		1,, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,
	full of branches and leaves. Only one	н				
3/14/2012	down spout on gutter.		17-Apr	27-Mar		4/13/2012?
3/11/2012	down spout on gatter.		17 / (p)	27 17101		1,20,2022.
	Gutter over the front of unit 131 plugged	н				
3/15/2012	and leaking badly onto building.		17-Apr	27-Mar		4/13/2012?
3/13/2012			17-Api	27-IVIAI		4/13/2012:
0/45/0040	Gutter at parking spot 40 leaking at end	Н				1/12/20122
3/15/2012	сар.		17-Apr	27-Mar	Replacing this gutter	4/13/2012?
	Gutter over the front of unit 333 plugged	н				
4/11/2012	and leaking badly.		1-May	24-Apr		4/13/2012?
	Gutter over the 3rd bed room of unit 336	н				
4/11/2012	plugged and leaking badly.	п	1-May	24-Apr		
	Gutter over the 3rd bed room of unit 531					
6/13/2012	plugged and leaking.	н				
0,10,2012	P. 40800 4114 (0411116)					
	Land on lakeside bldg 1 needs grading	н			Tree was removed, work order issued for lawn repair to	
2/8/2012	(where duck fence was replaced)			28-Feb-12	the landscaper	
2/0/2012				20-100-12	the landscaper	-
	Uneven Concrete and gaps noted in walk					
	ways around complex. Could pose tripping	н				
3/14/2012	hazard. (See separate list)					
	Canopy outside unit 411 needs to be					
5/9/2012	replaced. In danger of falling down.	H				
	Dion Raymond has a hole in his wall left	Н				
6/13/2012	over from plumbing repair.	11				
0/10/005		н				
6/13/2012	Fireplace separating from wall in unit 325					
	Small lights that illuminate the entrance				The underground line feeding the sign lights has failed.	
11/9/2011	sign (in the island) not working.	M	12-Feb		Will need Board approval for repair. Being Bid.	
			12-L60			
11/9/2011	One Additional Walkway light needed.	M			Currently being bid	

4/11/2012	Walkway light out (The one immediately north of the one needing a second light)	М				
7/11/2012	Several security lights out on carports. (See		 			
6/13/2012	separate list)	M				
11/9/2011	Window specifications needed.	M			After speaking to several architects, one is sending me standard ASTM window installation guidelines. He said this may very well provide the guidance we need and solve the issue without involving an architect at each installation.	
11/9/2011	Open cable box outside of 113	М		1/2/2012	To Comcast, ticket #CR 274899954 (Box still open 05/09/2012)	
1/11/2012	Fir tree in front of unit 115 cut back but still has branches hanging over roof. Branches still laying on maintenance shed.	М				
6/13/2012	Tree on north side of Bldg 1 has several dead limbs.	М				
5/9/2012	Grass in several spots appears to be dying.	М				
6/13/2012	Cracks found in living room ceiling of unit 132	М				
6/13/2012	One end of Balcony in unit 535 dropped a couple inches	М				
6/13/2012	Unit 123 storage room door rotted through	М				
5/9/2012	Drainage problem at unit 214	M			Have one bid. Board wants additional bids	
5/9/2012	Gravel needed around walkways and swell at bldgs 4 & 5	s				
3/14/2012	Exterior siding on lakeside near unit 135 is bowing out. Could allow water intrusion.	S				
11/9/2011	Fire alarm system install	S				
11/9/2011	Hot Tub repairs	S			Collecting bids for this work, looks like there will be funds available this year to do it.	
5/9/2012	Threshold boards in the bathrooms of the Cabana are broken.	s				
5/9/2012	Cabana Fireplace screen needs repair/replace	S				
11/9/2011	Repaint speed bumps	S			Should wait until spring & warmer weather	
6/13/2012	Carpet on many stairwell landings need to be replaced	s				
Driorities	High - As soon as nossible	2.4.11	um - Within a m		Schedule - When funds and scheduling nermi	

LSV Concrete Walkways Needing Repair

April 27, 2010 list

- 1. Building walkway between 3 & 4 End by parking spot #44 broken.
- 2. Connect sidewalk at Building 2 & replace adjoining sections Uneven sections with root damage.
- 3. Walkway in front of building 1 near units 111 & 112, spalled, 2 sections Verified.
- 4. Walkway in front of building 1 near units 113 & 114, replace 1 section Replaced
- 5. Entry area at units 111 & 112, sagging causing constant wet area. Verified
- 6. Walkway in front of building 2, 2 sections spalling. Verified
- 7. Entrance walkway leading to units 313 & 314 Needs leveling
- 8. Entrance walkway leading to units 315 & 316. Needs grinding
- 9. Behind unit 411, entry to gazebo area. Uneven and spalling
- 10. Entry area at units 513 & 514, appearance issue. Needs coating

June 11, 2012 Walk around

- 1. Walkway at units 211 & 212 uneven due to tree roots
- 2. Walkway at units 213 & 214 has broken concrete
- 3. Concrete at south end of bridge has tree root damage
- 4. Walkway by lake gate separating
- 5. Walkway behind building 4 needs grinding
- 6. Walkway between buildings 4 & 5 separating
- 7. Walkway between units 412 and 413 needs grinding
- 8. Walkway in front of Cabana needs grinding
- 9. Curb by the pool parking is broken.

LSV Light Bulb Replacement List

- 1. Canopy light at parking spot 68/69
- 2. Security light on canopy between spots 2/3
- 3. Security light on canopy at spot 56
- 4. Light on the end of canopy at spot 48
- 5. Light on the end of canopy at spot 31
- 6. Light on the end of canopy at spot 9
- 7. Light on the end of canopy at spot 5
- 8. Entrance light on right side as you are entering