Minutes of the Lakeside Village Combined Committee Meeting

May 09, 2012 at 7:00PM

1. Introductions/Role Call -

Absent
Х
X

Roland Draughon – Home Owner (532) Dion Raymond – Board Member (414) Frank Slattery – Home Owner (523)

2. Maintenance and Grounds (M&G) Issues -

a. Follow-up from last meeting -

The April 2012 Action Item Tracking Sheet was reviewed.

b. Fire Alarm System -

Dion and I presented our review of the final four contractors selected to install the fire alarm system. We felt that all four would be able to professionally install the alarms in our condominium complex. With their abilities being equal, we then looked at pricing. Based on all factors, we recommended that All Wire be selected to install the system and that Mountain Electric be selected to install monitoring equipment, perform the system annual inspection, and monitor the system once installed. The Committee by unanimous vote concurred with our recommendation.

c. New Items -

The May 2012 Action Item Tracking Sheet was annotated (see attached).

- 3. Communication Issues
 - a. Follow-up from last meeting No items were discussed.
 - b. New Items A new page was added to the Website concerning disaster preparedness.
- 4. Community Watch Status -

A presentation to residents at a future combined Board and Committee meeting would be the next step.

- 6. New committee members
 - a. Frank and Roland volunteered to join the Committee.
 - b. We still need new Committee Members from Buildings 1, 2, and 4.
- 7. Adjourn The meeting adjourned at 8:45PM.

Submitted by Jim Johnson

Attachment:

May Action Item Tracking Sheet

Lakeside Village Maintenance & Grounds Committee Action Item Tracking for May, 2012

		Board or	Estimated			
		Committee	Completion	Work order		Date
Date Added	Name/ Task	Priority	Date	Issue Date	Property Manager Status	Complete
11/17/2011	Gutters Bldg 5 (check on another way to prevent overflowing)	Н	17-Apr			
12/11/2001	Gutter at parking spot 4 rusted through/leaking and full of leaves. Downspout crushed shut. Gutter at parking spot 16 full of branches	Н	17-Apr	27-Mar		4/13/2012 ?
2/8/2012	Gutter at parking spot 16 full of branches and leaves.	н	17-Apr	27-Mar		4/13/2012 ?
3/14/2012	Gutters on street side of parking spot 72 full of branches and leaves. Only one down spout on gutter.	Н	17-Apr	27-Mar		4/13/2012?
3/15/2012	Gutter over the front of unit 131 plugged and leaking badly onto building.	Н	17-Apr	27-Mar		4/13/2012?
3/15/2012	Gutter at parking spot 40 leaking at end cap.	Н	17-Apr	27-Mar	Replacing this gutter	4/13/2012?
4/11/2012	Gutter over the front of unit 333 plugged and leaking badly.	Н	1-May	24-Apr		4/13/2012?
4/11/2012	Gutter over the 3rd bed room of unit 336 plugged and leaking badly.	Н	1-May	24-Apr		
2/8/2012	Land on lakeside bldg 1 needs grading and 30 ft of duck fence needs to be replaced.	Н		28-Feb-12	Tree was removed, work order issued for lawn repair to the landscaper & bid request out for fence replacement	
3/14/2012	Uneven Concrete and gaps noted in walk ways around complex. Could pose tripping hazard.	Н				
5/9/2012	Canopy outside unit 411 needs to be replaced. In danger of falling down.	Н				
5/9/2012	Men's room toilet in Cabana stopped up and over flowed. No toilet tissue.	н				
11/9/2011	Small lights that illuminate the entrance sign (in the island) not working.	M	12-Feb		The underground line feeding the sign lights has failed. Will need Board approval for repair.	
11/9/2011	One Additional Walkway light needed.	M			Currently being bid	

standard ASTM window inst this may very well provide t solve the issue without invo installation. 11/9/2011 Open cable box outside of 113 M 1/2/2012 O5/09/2012) 12/8/2011 Cabana front door needs weather stripping (Completed by Roland) M 1/2/2012 O5/09/2012) 12/8/2011 Fir tree in front of unit 115 cut back but still has branches hanging over roof. Branches still laying on maintenance shed. Grass in several spots appears to be dying. Gravel needed around walkways and swell at bldgs 4 & 5 S Exterior siding on lakeside near unit 135 is bowing out. Could allow water intrusion. 11/9/2011 Fire alarm system install S Threshold boards in the bathrooms of the Cabana are broken. M Collecting bids for this work funds available this year to solve the issue without this may very well provide t solve this solve the issue without this may very well provide t solve the issue without invoinstallation. To Comcast, ticket #CR 2748 05/09/2012 O5/09/2012) M J/2/2012 M OF		
11/9/2011 Open cable box outside of 113 M 1/2/2012 05/09/2012) 12/8/2011 Cabana front door needs weather stripping (Completed by Roland) Fir tree in front of unit 115 cut back but still has branches hanging over roof. Branches still laying on maintenance shed. Grass in several spots appears to be dying. Gravel needed around walkways and swell at bldgs 4 & 5 Exterior siding on lakeside near unit 135 is bowing out. Could allow water intrusion. 11/9/2011 Fire alarm system install Threshold boards in the bathrooms of the Cabana are broken. M 1/2/2012 05/09/2012 M M M A I/2/2012 05/09/2012) M A A A A A A A A A A A A	ne guidance we need and	
12/8/2011 (Completed by Roland) Fir tree in front of unit 115 cut back but still has branches hanging over roof. Branches still laying on maintenance shed. Grass in several spots appears to be dying. Gravel needed around walkways and swell at bldgs 4 & 5 Exterior siding on lakeside near unit 135 is bowing out. Could allow water intrusion. 11/9/2011 Fire alarm system install Threshold boards in the bathrooms of the Cabana are broken. M M Collecting bids for this work funds available this year to the Cabana are broken.	99954 (Box still open	
but still has branches hanging over roof. Branches still laying on maintenance shed. Grass in several spots appears to be dying. Gravel needed around walkways and swell at bldgs 4 & 5 Exterior siding on lakeside near unit 135 is bowing out. Could allow water intrusion. 11/9/2011 Fire alarm system install 11/9/2011 Hot Tub repairs Threshold boards in the bathrooms of 5/9/2012 the Cabana are broken. M M Collecting bids for this work funds available this year to describe the Cabana are broken.		May
Grass in several spots appears to be dying. Gravel needed around walkways and swell at bldgs 4 & 5 Exterior siding on lakeside near unit 135 is bowing out. Could allow water intrusion. 11/9/2011 Fire alarm system install S Collecting bids for this work funds available this year to describe the Cabana are broken.		
5/9/2012 swell at bldgs 4 & 5 Exterior siding on lakeside near unit 135 is bowing out. Could allow water intrusion. 11/9/2011 Fire alarm system install S Collecting bids for this work funds available this year to 6 the Cabana are broken.		
3/14/2012 bowing out. Could allow water intrusion. 11/9/2011 Fire alarm system install S Collecting bids for this work funds available this year to a solution of the Cabana are broken. S S Collecting bids for this work funds available this year to a solution of the Cabana are broken.		
11/9/2011 Hot Tub repairs S Collecting bids for this work funds available this year to a solution of the Cabana are broken.		
11/9/2011 Hot Tub repairs S funds available this year to a fund a fund a fund a fund available this year to a fund a fund available this year to a fund a fund available this year to a fund a fund a fund a fund available this year to a fund a fund available this year to a fund a fund available this year to a fund a fund a fund a fund available this year to a fund a fund available this year to a fund a fund available this year to a fund a fund a fund a fund available this year to a fund a fun	ľ	
5/9/2012 the Cabana are broken.		
Cabana Fireplace screen needs 5/9/2012 repair/replace		
11/9/2011 Repaint speed bumps S Should wait until spring 8	warmer weather	

Priorities

High = As soon as possible

Medium = Within a month

Schedule = When funds and scheduling permit