## Minutes of the Lakeside Village Combined Committee Meeting

## April 11, 2012 at 7:00PM

1. Introductions/Role Call -

Committee Members	Committee	Present	Absent
Bob Hester (531)	С	Х	
Jim Johnson – Board Rep (324)		Х	
Dorothy Montgomery (325)	M&G	Х	
Michelle Moodie (211)	С	Х	
Nancy Nolan (111)	M&G		X
Tom O'Keefe (313)	С	Х	

Roland Draughon – Home Owner (532)

- 2. Maintenance and Grounds (M&G) Issues
  - a. Follow-up from last meeting -

The March 2012 Action Item Tracking Sheet was reviewed.

b. Fire Alarm System -

The Committee had further discussion concerning the alarm system and its cost. I provided the current bid status and advised that we are still waiting for one more bid to come in. I will be getting bids from another 120 volt electrical installation company in the near future.

c. New Items -

The April 2012 Action Item Tracking Sheet was annotated (see attached).

Additional park benches were recommended.

Grass and lawn improvements were discussed.

A yard sale was discussed. The Committee recommended that it be held after school is out.

3. Communication Issues -

Follow-up from last meeting – No items were discussed.

4. Community Watch Status -

A presentation to residents, Board and Committee should be scheduled soon.

- 5. Disaster Preparedness preparation was discussed. Information and links will be placed on our website.
- 6. New committee members It was noted that we now need new Committee Members from Buildings 1, 2, 4, and 5.
- 7. Adjourn The meeting adjourned at 8:45PM.

Submitted by Jim Johnson

Attachment:

April Action Item Tracking Sheet

## Lakeside Village Maintenance & Grounds Committee Action Item Tracking for April, 2012

		Board or	Estimated			
		Committee	Completion	Work order		Date
Date Added	Name/ Task	Priority	Date	Issue Date	Property Manager Status	Complete
	Gutters Bldg 5 (check on another way to	<u>·</u>				
11/17/2011	prevent overflowing)	Н	17-Apr			
	Gutter at parking spot 4 rusted					
	through/leaking and full of leaves.	н				
12/11/2001	Downspout crushed shut. Gutter at parking spot 16 full of branches		17-Apr	27-Mar		
2/8/2012	and leaves.	н	17-Apr	27-Mar		
2/0/2012	Gutters on street side of parking spot 72		тлері	27-11101		
	full of branches and leaves. Only one	н				
3/14/2012	down spout on gutter.	п	17-Apr	27-Mar		
5/14/2012			тлей	27 10101		
	Gutter over the front of unit 131 plugged	н				
3/15/2012	and leaking badly onto building.	n n	17-Apr	27-Mar		
5/15/2012			17-Api	27-10101		
2/15/2012	Gutter at parking spot 40 leaking at end	н	17.1			
3/15/2012	сар.		17-Apr	27-Mar	Replacing this gutter	
	Gutter over the front of unit 333 plugged	н				
4/11/2012	and leaking badly.					
	Gutter over the 3rd bed room of unit 336	н				
4/11/2012	plugged and leaking badly.					
	Land on lakeside bldg 1 needs grading and					2
	30 ft of duck fence needs to be replaced.	н			Tree was removed, workorder issued for lawn repair to	
2/8/2012	na na - Unio na - Constructurana in prostantamente normana entrata entrata - entrata			28-Feb-12	the landscaper & bid request out for fence repalcement	
	Uneven Concrete and gaps noted in walk					
2/14/2012	ways around complex. Could pose tripping	н				
3/14/2012	hazard.					
	Small lights that illuminate the entrance	м			The underground line feeding the sign lights has failed.	
11/9/2011	sign (in the island) not working.	141	12-Feb		Will need Board approval for repair.	
11/9/2011	One Additional Walkway light needed.	М				
4/11/2012	Walkway light out	M				
11/9/2011	Paint storage room doors	M	12-Apr	10/22/2011	They are working to get those this month	
11/3/2011	ranic storage room doors	141	TZ-Whi	10/22/2011	They are working to get those this month	

11/9/2011	Window specifications needed.	M			After speaking to several architects, one is sending me standard ASTM window installation guidelines. He said this may very well provide the guidance we need and solve the issue without involving an architect at each installation. To Comcast, ticket #CR 274899954 <b>(Box still open</b>
11/9/2011	Open cable box outside of 113	М		1/2/2012	04/11/2012)
12/8/2011	Cabana front door needs weather stripping	м			
1/11/2012	Fir tree in front of unit 115 cut back but still has branches hanging over roof. Branches still laying on maintenance shed.	Μ			
3/14/2012	Exteriior siding on lakeside near unit 135 is bowing out. Could allow water intrusion.	S			
11/9/2011	Fire alarm system install	S			
11/9/2011	Hot Tub repairs	S			Collecting bids for this work, looks like there will be funds available this year to do it.
11/9/2011	Repaint speed bumps	S			Should wait until spring & warmer weather
Priorities	High = As soon as possible	Medi	um = Within a mo	onth	Schedule = When funds and scheduling permit