## Minutes of the Lakeside Village Combined Committee Meeting

## March 14, 2012 at 7:00PM

## 1. Introductions/Role Call -

Committee Members	Committee	Present	Absent
Bob Hester (531)	С	Х	
Jim Johnson – Board Rep (324)		Х	
Dorothy Montgomery (325)	M&G		Х
Michelle Moodie (211)	С		Х
Nancy Nolan (111)	M&G	Х	
Tom O'Keefe (313)	С		Х

Roland Draughon – Home Owner (532) Frank Slattery – Home Owner (523)

- 2. Maintenance and Grounds (M&G) Issues
  - a. Follow-up from last meeting -

The February 2012 Action Item Tracking Sheet was reviewed.

b. Fire Alarm System -

The Committee had further discussion concerning the alarm system and its cost. I proved the current bid status and advised that we are still waiting for three more bid to come in. I will be getting bids from two 120 volt electrical installation companies in the near future.

- c. Stephanie Dunning resigned from the Committee due to her new work schedule.
- d. New Items -

The March 2012 Action Item Tracking Sheet was annotated (see attached).

- 3. Communication Issues
  - a. Follow-up from last meeting No items were discussed.
  - b. New Items On the "News" page of the Website I added information about the fire alarm system.
- 4. Community Watch Status
  - a. A car belonging to unit 334 has been broken into twice during the past month.
  - b. A new page has been added to our Website, entitled "Crime". It contains statistics and a security checklist.
  - c. A presentation to residents at a future meeting would be the next step.
- 6. New committee members It was noted that we now need new Committee Members from Buildings 1, 2, 4, and 5.
- 7. Adjourn The meeting adjourned at 8:45PM.

Submitted by Jim Johnson

Attachment:

March Action Item Tracking Sheet

## Lakeside Village Maintenance & Grounds Committee Action Item Tracking for March 25, 2012

***************************************		Board or	Estimated			
		Committee	Completion	Work order		Date
Date Added	Name/ Task	Priority	Date		Property Manager Status	Complete
	Tamo, Tox	11101104		- Issue Bute	Toperty Manager Class	-
	Faucet repaired but wall in unit 111 needs					
	patching and plumber did not insulate	Н				
	pipe. Cut out piece of wall screwed back in					
11/9/2011	place, but not patched and painted.		27-Feb-12	1-Jun		
	Gutters Bldg 5 (check on another way to	Н				1
11/17/2011	prevent overflowing)					
12/8/2011	Fence post by bus stop leaning	Н	16-Apr	12-Mar		
	Gutter at parking spot 4 rusted	-				
12/11/2001	through/leaking and full of leaves.	Н				
12/11/2001	Downspout crushed shut. Gutter at parking spot 16 full of branches					
2/8/2012	and leaves.	н				
	Gutters on street side of parking spot 72					
	full of branches and leaves. Only one	н				
3/14/2012	down spout on gutter.					1
						l
	Gutter over the front of unit 131 plugged	Н				
3/15/2012	and leaking badly onto building.					1
	Gutter at parking spot 40 leaking at end					
3/15/2012	cap.	н				
3/13/2012						
2/25/2012	Gutter over the front of unit 333 plugged					
3/25/2012	and leaking badly.					
	Land on lakeside bldg 1 needs grading and					
2/2/2242	30 ft of duck fence needs to be replaced.	Н		00 5 1 40	Tree was removed, workorder issued for lawn repair to	]
2/8/2012				28-Feb-12	the landscaper & bid request out for fence repalcement	
	Dryer vent in unit 325 stopped up.	н				
3/15/2012	Reported at February Board Meeting.					
	Small lights that illuminate the entrance					
44/0/2245	sign (in the island) and flag pole light not	M	10 - 1			
11/9/2011	working.		12-Feb			
11/9/2011	One Additional Walkway light needed.	M				
11/9/2011	Paint storage room doors	M		10/22/2011	On hold until weather improves in the spring	

11/9/2011	Window specifications needed.	М			After speaking to several architects, one is sending me standard ASTM window installation guidelines. He said this may very well provide the guidance we need and solve the issue without involving an architect at each installation.
11/9/2011	Open cable box outside of 113	M		1/2/2012	To Comcast, ticket #CR 274899954 (Box still open 03/14/2012)
12/8/2011	Cabana front door needs weather stripping	M			
3/14/2012	Uneven Concrete and gaps noted in walk ways around complex. Could pose tripping hazard.	M			
1/11/2012	Trees need trimming (all buildings)	M			I have contcted the arborist to see what his availability is
3/14/2012	Exteriior siding on lakeside near unit 135 is bowing out. Could allow water intrusion.	S			
11/9/2011	Fire alarm system install	S			
11/9/2011	Hot Tub repairs	S			Collecting bids for this work, looks like there will be funds available this year to do it.
11/9/2011	Repaint speed bumps	S			Should wait until spring & warmer weather
11/9/2011	Cabana Stove working, but needs new door seal and cleaning.	S			Workorder issued
11/9/2011	Cabana Counter Top Edge Repair	S			
12/11/2012	Fence post by bldg 5 too short	S	16-Apr	12-Mar	With work order above.

Priorities

High = As soon as possible

Medium = Within a month

Schedule = When funds and scheduling permit